

## **BSI-Inspectorate America** 178 Mortland Road Searsport, Maine 04974 (207)548-6440

## **QUALITY CERTIFICATE**



Vessel Customer

Operation

SHORE TANK NO. 3

**SPRAGUE** 

**ANALYSIS** 

Port Date BUCKSPORT, MAINE

January 30, 2003

Terminal **SPRAGUE**  Report

SP/03/0203 Reference

Sample # 42928

Name of material being tested Description of sample source Samples Drawn by (company) Samples Tested by (company) NO. 6 FUEL OIL 0.5%

EX. SHORE TANK NO. 3 AFTER DISCHARGE OF B NO. 160 **INSPECTORATE INSPECTORATE** 

Tests being Performed	Test method	Minimum Maximum	Sample Source
GRAVITY, API @ 60 F FLASH POINT, F VISCOSITY, SSF @ 122 F POUR POINT, F WATER & SEDIMENT, % VOL. "LPHUR, % WT	ASTM D 4052 ASTM D 93 ASTM D 445/2161 ASTM D 97 ASTM D 1796 ASTM D 4294 ASTM D 482		15.7 200+ 63.7 +53.6 0.20 0.508 0.034
VANADIUM, PPM SODIUM, PPM BTU'S/POUND BTU'S/GALLON NITROGEN, % WT. CARBON RESIDUE, % WT.	AA/AE AA/AE CALCULATION CONVERSION ASTM D 3228 ASTM D 4530		17 23 18,707 149,750 0.371 6.39
ASPHALTENES, % WT.	IP-143		1.65
THE ATTACHED CERTIFICATE REPRESENTS THE BY THE INSPECTION SERVICE ON THE DATE SERVICE ON THE DATE SERVICE ON THE DATE SERVICE OF THE INSPECTION CERTIFICATE BUT SERVICE THE SPECIFICATIONS AS MAY BE REQUERED.	TATED ON THE SPECTION SERVICE. SPRAGUE LE AT THE RACK MAY DIFFER SUCH PRODUCT SHALL SIRED BY ANY APPLICABLE		